SAMSOF TECHNOLOGIES REPAIR SERVICES
Block 3, Lot 19, Phase 8, Carmona Estates
Brgy. Lantic, Carmona Cavite
Tel No. (02) 925-9160
Email: sales@samsof.com

Job Order No.Pricon-060917-01
Purchased Order No:

Service Report

Company :Pricon Microelectronics Inc.
Address : 14 Ampere St., Light Industry and Science Park 1, SEPZ, Cabuyao, Laguna
Requestor : :Mr. Virgilio Garcia

Project Details

Description :Repair of YASKAWA AC SERVO DRIVER
Brand : YASKAWA
Model No: SGDS-04A12AY27
Serial No. D0055C894220029
Quantity : 1pc
History/Problem :
> Alarm
>Vibration
>

Project Description

- [x] Board Repair
- [ ] Preventive Maintenance (PM)
- [ ] Assessment
- [ ] Others (Machine repair and isoltaion)

To be filled up by Samsof Service Engineers.

Activity Done :

> Checked all possible defective parts using huntron signature analyzer.
>Found out leaky electrolytic capacitor.5pcs
>Found out defective IGBT MODULE.
>Found out leaky rectifier diode.
> Clean all contacts and terminals .
> Checked and resolder all possible weak solder on board.
> Replaced all found out defective components on board.
> Tested in running machine.
> Confirmed Good. Machine now can initialized.

REPAIR ASSESSMENT RESULT

- [x] Passed
- [ ] Failed / For Further Repair and Cheking
- [ ] Un-repairable
- [ ] For Machine Testing Evaluation
- [ ] waiting for parts
- [ ] waiting for customer advice.

Remarks:
> Tested Good,. Installed at running machine.

Prepared By:

ANGELO CANON/ 06/09/2017
SAMSOF REPRESENTATIVE / DATE

Verified By:

Authorized Representative / Date