RELIANCE COR. BRIXTON STS., PASIG CITY
TELS.: 631-1775 TO 84 • FAX: (632) 631-4028
EMAIL : mesco@mesco.com.ph
Website : http://www.mesco.com.ph

MESCO INC. Since 1956

QUALITY MACHINE TOOLS & ENGINEERING PRODUCTS

SR № 102338

EC VALIDATION STATUS (Internal Use Only)
a) Customer and Machine Info ☐ OK ☐ NG
b) Workpiece ☐ OK ☐ NG

SERVICE REPORT

CUSTOMER: PRICON
ADDRESS: LISP
MACHINE: VA1-11
SERIAL NO.: 10112A CODE NO.:

SERVICEMAN: AAR
DATE: JULY 23, 2018
TIME START: 11:30 AM
TIME FINISH: 12:30
TOTAL HRS.: 1 HR TRAVELLING HOURS: 1 HR

JOB COMPLETED: ☑ YES ☐ NO
INSTALLATION DATE:
WARRANTY: ☐ YES ☑ NO

REPORTED PROBLEM: ATC PROBLEM

WORK TYPE:
☐ Calibration ☐ Repair:
☐ PM ☐ Training:
☐ Installation ☐ Parts Measurement:
☐ Shifting ☐ Others:

WORK DONE:

- CHECK M/C PROBLEM
- FOUND ATC IS NOT IN ZERO POSITION
- OPEN ATC PARAMETER
- POSITION ATC IN ZERO POSITION
- POWER OFF/ON M/C
- PERFORM TOOL CHANGE.
- FOUND OK!
- M/C IS NOW BACK IN OPERATION.

☐ PARTS REPLACED ☐ PARTS TO BE REPLACED

PARTS NO.	DESCRIPTION	QTY.
N	N	N

RECOMMENDATIONS:

REMARKS:

PERSON IN CHARGE: N. Mendoza
POSITION: Sr. Engineer
SIGNATURE:

WHITE - ORIGINAL COPY YELLOW - DEPARTMENT COPY PINK - CUSTOMER COPY

Scanned with CamScanner