

IANet Accurate Nationwide Appraisals - Staff

Workfile ID:

4a611da2

<https://ianetwork.net/supplements/>
2425 East Camelback Road Suite 150
PHOENIX, AZ 85050
Phone: (480) 596-1105, FAX:(480) 596-1140
supplements@ianetwork.net

For:

IANET, INC

HOME STATE COUNTY MUTUAL INSURANCE COMPANY
National General Insuranc

Estimate of Record

Owner: Muscara, Gregory

Job Number:

Written By: John Fullerton
Adjuster: Peterson, Erik

Insured: Muscara, Gregory
Type of Loss: Collision
Point of Impact: 01 Right Front

Policy #:
Date of Loss: 5/1/2026 5:00 AM

Claim #: 260479295-1
Days to Repair: 0

Owner:
Muscara, Gregory
321 S WATSON ST
Alvarado, TX 76009
(682) 366-5115 Cell

Inspection Location:
Maaco Collision Repair Auto Paint
216 EXCHANGE STREET
Burleson, TX 76028
Repair Facility
(817) 880-6267 Day

Repair Facility:
MAACO COLLISION-BURLESON
216 EXCHANGE ST
BURLESON, TX 76028
(817) 880-6267 Business

VEHICLE

2026 TOYO Tundra 4WD SR CrewMax w/5.5' Bed 4D SHORT 6-3.4L Turbocharged Gasoline Port/Direct Injection GRAY

VIN: 5TFKB5DB1TX376956
License: WPM9431
State: TX

Production Date: 12/2025
Odometer: 12,950
Condition: Good

Interior Color:
Exterior Color: GRAY

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors

DECOR

Dual Mirrors
Privacy Glass

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera

Remote Starter

Intelligent Cruise

Search/Seek

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Communications System

Cloth Seats

Bucket Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

California Emissions

TRUCK

Rear Step Bumper

Power Rear Window

Bedliner

Trailer Hitch

Estimate of Record

Owner: Muscara, Gregory

Job Number:

2026 TOYO Tundra 4WD SR CrewMax w/5.5' Bed 4D SHORT 6-3.4L Turbocharged Gasoline Port/Direct Injection GRAY

Console/Storage	RADIO	Hands Free Device	Trailer Package
Overhead Console	AM Radio	Xenon or L.E.D. Headlamps	
CONVENIENCE	FM Radio	Lane Departure Warning	
Air Conditioning	Stereo	SEATS	

Estimate of Record

Owner: Muscara, Gregory

Job Number:

2026 TOYO Tundra 4WD SR CrewMax w/5.5' Bed 4D SHORT 6-3.4L Turbocharged Gasoline Port/Direct Injection GRAY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPER						
2	*	R&I RT Side cover w/o park aid, w/o off road pkg				<u>0.2</u>	
3	* <>	Rpr RT Side cover w/o park aid, w/o off road pkg				<u>1.5</u>	1.7
4		Add for Clear Coat					0.7
5	Repl	Upper support	531130C060	1	117.08	0.2	
6	GRILLE						
7	Repl	Grille assy SR	531010C110	1	298.72	0.3	
8	FRONT LAMPS						
9	Repl	RT Headlamp assy	811400C230	1	868.92	0.2	
10		Aim headlamps				0.5	
11	R&I	LT Headlamp assy				0.2	
12	RADIATOR SUPPORT						
13		Refinish Components					1.8
14		Overlap Major Non-Adj. Panel					-0.2
15		Add for Clear Coat					0.3
16	Repl	Upper tie bar	532050C070	1	134.05	0.3	Incl.
17	Repl	RT Side support	532020C050	1	351.12	3.2	Incl.
18	HOOD						
19	Repl	Hood w/o molding (ALU)	533010C070	1	884.89	1.6	3.0
20		Overlap Major Non-Adj. Panel					-0.2
21		Add for Clear Coat					0.6
22		Add for Underside(Complete)					1.5
23		Add for Clear Coat					0.3
24	Repl	Lock assy	535100C090	1	104.77	0.3	
25	Repl	RT Hinge	534100C040	1	55.54	0.3	0.6
26		Overlap Minor Panel					-0.2
27		Add for Clear Coat					0.1
28	Repl	LT Hinge	534200C040	1	55.54	0.3	0.6
29		Overlap Minor Panel					-0.2
30		Add for Clear Coat					0.1
31	FENDER						
32	Repl	RT Fender w/o TRD pkg	538110C120	1	341.14	2.2	2.2
33		Overlap Major Adj. Panel					-0.4
34		Add for Clear Coat					0.4
35		Add for Edging					0.5
36		Add for Clear Coat					0.1
37	*	Blnd LT Fender w/o TRD pkg					<u>1.1</u>
38	R&I	RT Fender liner w/tow pkg				Incl.	
39	R&I	LT Fender liner w/tow pkg				0.3	
40	FRONT SUSPENSION						
41	Repl	RT Rotor	435120C030	1	120.58 m	Incl.	

Estimate of Record

Owner: Muscara, Gregory

Job Number:

2026 TOYO Tundra 4WD SR CrewMax w/5.5' Bed 4D SHORT 6-3.4L Turbocharged Gasoline Port/Direct Injection GRAY

42	Repl	RT Hub assy	435500C010	1	625.24 m	2.3 M	
43	Repl	RT Caliper	477300C060	1	277.76 m	0.7 M	
44		Bleed brake system four wheel			m	1.7 M	
45	Repl	Brake pads from 05/2025	0446534050	1	144.52	Incl.	
46	Repl	RT Knuckle	432010C010	1	518.29 m	Incl.	
47		Deduct for Overlap				-0.3 M	
48	FRONT DOOR						
49	*	Blnd	RT Outer panel (ALU)				<u>1.2</u>
50	*	R&I	RT Belt molding gloss black			<u>0.3</u>	
51		R&I	RT R&I mirror			0.3	
52		R&I	RT Handle, outside non-painted black			0.4	
53		R&I	RT R&I trim panel			0.5	
54	MISCELLANEOUS OPERATIONS						
55	#		Cover Car	1	5.00	0.2	
56	#	Subl	Four wheel alignment	1	99.95		
57	#	Rpr	Rough Pull			1.0 F	
58	#	Rpr	Setup & measure			2.0 F	
SUBTOTALS					5,003.11	20.7	15.6

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				5,003.11
Body Labor	13.3 hrs	@	\$ 58.00 /hr	771.40
Paint Labor	15.6 hrs	@	\$ 58.00 /hr	904.80
Mechanical Labor	4.4 hrs	@	\$ 125.00 /hr	550.00
Frame Labor	3.0 hrs	@	\$ 58.00 /hr	174.00
Paint Supplies	15.6 hrs	@	\$ 45.00 /hr	702.00
Subtotal				8,105.31
Sales Tax	\$ 5,705.11	@	8.2500 %	470.67
Total Cost of Repairs				8,575.98
Deductible				500.00
Total Adjustments				500.00
Net Cost of Repairs				8,075.98

THIS IS NOT AN AUTHORIZATION TO REPAIR. REPAIR AUTHORIZATION MUST BE OBTAINED FROM THE VEHICLE OWNER.

NO SUPPLEMENT WILL BE HONORED WITHOUT PRIOR APPROVAL/INSPECTION BY APPRAISER AND INSURANCE CO.

COPIES OF ALL INVOICES FROM THE ENTIRE REPAIRS MUST BE PROVIDED.

ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT INSURANCE CLAIM FOR THE PAYMENT OF A LOSS MAY BE GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE PRISON

Owner: Muscara, Gregory**Job Number:**

2026 TOYO Tundra 4WD SR CrewMax w/5.5' Bed 4D SHORT 6-3.4L Turbocharged Gasoline Port/Direct Injection GRAY

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8194, CCC Data Date 05/08/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.
X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.
M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.
CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.
D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part.
O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet.
UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Estimate of Record

Owner: Muscara, Gregory

Job Number:

2026 TOYO Tundra 4WD SR CrewMax w/5.5' Bed 4D SHORT 6-3.4L Turbocharged Gasoline Port/Direct Injection GRAY

ALTERNATE PARTS USAGE

2026 TOYO Tundra 4WD SR CrewMax w/5.5' Bed 4D SHORT 6-3.4L Turbocharged Gasoline Port/Direct Injection GRAY

VIN:	5TFKB5DB1TX376956	Production Date:	12/2025	Interior Color:	
License:	WPM9431	Odometer:	12,950	Exterior Color:	GRAY
State:	TX	Condition:	Good		

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	2	0
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0