

Customer Site Location (WG84)

Inspection Date Project Manager

1.Broken_Glass

Defect Details

Module No.	(10, 6)
Table No.	B1/T67

Temperature Details

Minimum Temperature	28.88999939(°C)
Maximum Temperature	41.86999893(°C)
Average Temperature	37.9(°C)
Delta(Δ) Temp.(°C)	(°C)

Layout Location Details

Latitude	28.43509
Longitude	28.43509

Thermal



Rgb



2.Broken_Glass

Defect Details

Module No.	(12, 15)
Table No.	B1/T24

Temperature Details

Minimum Temperature	33.72000122(°C)
Maximum Temperature	52.54999924(°C)
Average Temperature	43.41(°C)
Delta(Δ) Temp.(°C)	(°C)

Layout Location Details

Latitude	28.43605
Longitude	28.43605

Thermal



Rgb



3.Broken_Glass

Defect Details

Module No.	(7, 15)
Table No.	B1/T24

Temperature Details

Minimum Temperature	24.87000084(°C)
Maximum Temperature	51.29999924(°C)
Average Temperature	44.96(°C)
Delta(Δ) Temp.(°C)	(°C)

Layout Location Details

Latitude	28.43605
Longitude	28.43605

Thermal
defect1
Rgb
defect2

4.Broken_Glass

Defect Details

Module No.	(11, 13)
Table No.	B1/T11

Temperature Details

Minimum Temperature	33.70999908(°C)
Maximum Temperature	43.90000153(°C)
Average Temperature	40.01(°C)
Delta(Δ) Temp.(°C)	(°C)

Layout Location Details

Latitude	28.43431
Longitude	28.43431

Thermal



Rgb



5.Broken_Glass

Defect Details

Module No.	(11, 15)
Table No.	B1/T11

Temperature Details

Minimum Temperature	28.81999969(°C)
Maximum Temperature	43.61999893(°C)
Average Temperature	39.17(°C)
Delta(Δ) Temp.(°C)	(°C)

Layout Location Details

Latitude	28.43434
Longitude	28.43434

Thermal
defect1
Rgb
defect2

6.Broken_Glass

Defect Details

Module No.	(4, 15)
Table No.	B1/T11

Temperature Details

Minimum Temperature	36.11999893(°C)
Maximum Temperature	46.54000092(°C)
Average Temperature	42.34(°C)
Delta(Δ) Temp.(°C)	(°C)

Layout Location Details

Latitude	28.43434
Longitude	28.43434

Thermal



Rgb



7.Broken_Glass

Defect Details

Module No.	(8, 6)
Table No.	B1/T11

Temperature Details

Minimum Temperature	30.45999908(°C)
Maximum Temperature	46.95000076(°C)
Average Temperature	43.08(°C)
Delta(Δ) Temp.(°C)	(°C)

Layout Location Details

Latitude	28.43424
Longitude	28.43424

Thermal



Rgb



8.Broken_Glass

Defect Details

Module No.	(7, 6)
Table No.	B1/T11

Thermal
defect1
Rgb
defect2

Temperature Details

Minimum Temperature	30.97999954(°C)
Maximum Temperature	46.86000061(°C)
Average Temperature	42.91(°C)
Delta(Δ) Temp.(°C)	(°C)

Layout Location Details

Latitude	28.43424
Longitude	28.43424