OFFICIAL LABORATORY INSPECTION REPORT

Facility Location: Analytical Research Facility Sector 7

Status: Verified Compliant under Biosafety Level 2 Standards

1. Ventilation and airflow mechanisms passed the pressure differential test.

2. Chemical containment storage cabinets were securely locked and labeled.

3. Emergency eyewash stations were flushed and operational.