OFFICIAL LABORATORY INSPECTION REPORT

Facility Location: Analytical Research Facility Sector 7

Status: Verified Compliant under Biosafety Level 2 Standards

1. Ventilation and airflow mechanisms passed the pressure differential test.

2. Chemical containment storage cabinets were securely locked and labeled.

3. Emergency eyewash stations were flushed and operational.

RECORD ID: BATES-0049281-CONFIDENTIAL-DISTRICT-COURT-ARCHIVE