

1234 Elm Street, Building A

Date: 20 September, 2024

Property Address: 1234 Elm Street, Building A


Warden: James Baker

Start Time: 9:00 AM


Complete Time: 5:00 PM

Property Images


The photos included in this report were taken at determined and random intervals throughout the fire watch shift. Each photo is time-stamped and geo-tagged to verify the presence of the fire watch personnel on-site, demonstrating active patrols and attentiveness. This documentation ensures compliance with fire watch duties and provides evidence of on-site activity for review by the client and the Authority Having Jurisdiction (AHJ).




🕒 9:30 AM




🕒 9:30 AM




🕒 9:30 AM




🕒 9:30 AM




🕒 9:30 AM




🕒 9:30 AM




🕒 9:30 AM



🕒 9:30 AM




🕒 9:30 AM



🕒 9:30 AM




🕒 9:30 AM




🕒 9:30 AM




🕒 9:30 AM




🕒 9:30 AM



🕒 9:30 AM




🕒 9:30 AM



🕒 9:30 AM



🕒 9:30 AM




🕒 9:30 AM



🕒 9:30 AM

Tracker Image

This section provides a visual representation of the fire watch personnel's location data throughout the shift. The map displays the patrol route, with location points captured continuously and movements detected in real-time. Instances of leaving the designated geofence radius are also recorded and highlighted to maintain transparency and accountability. This tracking ensures compliance with the fire watch requirements and provides verification of on-site presence for review by the client and the Authority Having Jurisdiction (AHJ).



Total Distance Covered: 14 km

Number of Steps: 224

Total Time: 9hr 3mins

Report Incident: **Yes**

Incident Title: Incident title

Incident Type: Fire

Incident Location: Balcony

Incident Time: 8:55 AM

Incident Description:

Lorem ipsum dolor sit amet, consectetur adipiscing elit, sed do eiusmod tempor incididunt ut labore et dolore magna aliqua

REDLINE

FIRE WATCH

Date: 20 September, 2024

Time: 12:30 AM - 4:00 PM

Property Name	Address	Building No.	Warden
Jefferson on the Cliffs	Block 12, Arlington TX 76006	343	Christopher Lint

Time	Name	All Clear	Note
12:30 pm	Jake Grove	X	(shift note)
1:00 pm	Jake Grove	X	(shift note)
1:30 pm	Jake Grove	X	(shift note)
2:00 pm	Jake Grove	X	(shift note)
2:30 pm	Jake Grove	X	(shift note)
3:00 pm	Jake Grove	X	(shift note)
3:30 pm	Jake Grove	X	(shift note)
4:00 pm	Jake Grove	X	(shift note)

Per NFPA 1:13:1:9 – When a fire protection system is out of service for more than 4 hours in a 24-hr period, the AHJ shall be permitted to require the building to be evacuated or an approved fire watch to be provided for all portions left unprotected by the fire protection system shutdown until the fire protections system has been returned to service.

Tampa

tampa@redlinefirewatch.com

656-222-0695

redlinefirewatch.com