



## Sertifikat Lengujian

## Tested Certificate

NO: 416114

## A. DATA ALAT

Instrumen Identification

Nama

: Phototherapy

Name

Merk Manufacturer : GE

Tipe

: Lullaby

Type

No.Seri

: SDW11392293PA

Serial Number

## B. <u>IDENTITAS PELANGGAN</u>

Customer Identification

Nama Name

: RSD Gunung Jati

Alamat Address

: Jl. Kesambi No.56, Kesambi, Kec. Kesambi,

Kota Cirebon - Jawa Barat 45134

Sertifikat Ini Terdiri Dari : 2 Halaman

This Certificate comprises of

Diterbitkan Tanggal : 20 September 2022

Date of Issue

Kalibrasi Berikutnya : 19 September 2023

Next Calibration

Kepala Laboratorium Kalibrasi

Head Of Calibration Laboratorium

PT. GLOBAL PROMEDIKA SERVICES

Hamzah, S.T.

- Tidak diperkenankan mengutip/memperbanyak sertifikat ini tanpa seizin dari PT. Global Promedika Services.
  Sertifikat ini sah apabila telah dibubuhi cap PT. Global Promedika Services dan telah ditandatangani oleh pejabat yang berwenang.
  Hasil kalibrasi ini hanya berlaku untuk alat yang tertera pada Sertifikat ini.
- This certificate shall not be reproduced except in full unless permission for the reproduction of an approced abstract has been obtained in writing from PT. Global Promedika Services
- This certificate is valid if it has ben approved and signed by authorized person.
  This result of calibration to be applied only for unit under test.

PT. GLOBAL PROMEDIKA SERVICES

Gedung Bersaudara It. 4A, Jl. Penjernihan Raya No. 38 Jakarta Pusat 10210. Telp. (021) 5743280, 5701467

Halaman 1 dari 2

www.globalpromedika.co.id