

# Sertifikat Kalibrasi

## Calibration Certificate

NO: 399417

### A. DATA ALAT

#### Instrumen Identification

**Nama** : Bed Side Monitor  
*Name*  
**Merk** : Drager  
*Manufacturer*  
**Tipe** : Vista 120  
*Type*  
**No.Seri** : V3SFN0029  
*Serial Number*

### B. IDENTITAS PELANGGAN

#### Customer Identification

**Nama** : RSUP Prof. dr. R. D. Kandou Manado  
*Name*  
**Alamat** : Jl. Raya Tanawangko No.56, Malalayang Satu Barat,  
*Address* Kec. Malalayang, Kota Manado, Sulawesi Utara

**Sertifikat Ini Terdiri Dari** : 3 Halaman  
*This Certificate comprises of*

**Diterbitkan Tanggal** : 07 Juli 2022  
*Date of Issue*

**Kalibrasi Berikutnya** : 06 Juni 2023  
*Next Calibration*

**Kepala Laboratorium Kalibrasi**  
*Head Of Calibration Laboratorium*  
**PT. GLOBAL PROMEDIKA SERVICES**



**Hamzah, S.T.**

- Tidak diperkenankan mengutip/memperbanyak sertifikat ini tanpa seizin dari PT. Global Promedika Services.
- Sertifikat ini sah apabila telah dibubuhi cap PT. Global Promedika Services dan telah ditandatangani oleh pejabat yang berwenang.
- Hasil kalibrasi ini hanya berlaku untuk alat yang tertera pada Sertifikat ini.

- This certificate shall not be reproduced except in full unless permission for the reproduction of an approved abstract has been obtained in writing from PT. Global Promedika Services.
- This certificate is valid if it has been approved and signed by authorized person.
- This result of calibration to be applied only for unit under test.

Halaman 1 dari 3