



## Sertifikat Pengujian

**Tested Certificate** 

NO: 410934

## DATA ALAT

Instrumen Identification

: Microscope Nama Name

Merk : Leica

Manufacturer

Tipe : DM 1000

: 407937 No.Seri Serial Number

## **IDENTITAS PELANGGAN**

Customer Identification

: RSUD Sekayu Nama

Name

: Jl. Kol. Wahid Udin, Kayu Ara, Sekayu Alamat Kab. Musi Banyuasin, Sumatera Selatan Address

Sertifikat Ini Terdiri Dari : 2 Halaman

This Certificate comprises of

Diterbitkan Tanggal : 03 Agustus 2022

Date of Issue

Kalibrasi Berikutnya : 02 Agustus 2023

**Next Calibration** 

Kepala Laboratorium Kalibrasi

Head Of Calibration Laboratorium

PT. GLOBAL PROMEDIKA SERVICES

- Tidak diperkenankan mengutip/memperbanyak sertifikat ini tanpa seizin dari PT. Global Promedika Services.
- Sertifikat ini sah apabila telah dibubuhi cap PT. Global Promedika Services dan telah ditandatangani oleh pejabat yang berwenang.
   Hasil kalibrasi ini hanya berlaku untuk alat yang tertera pada sertifikat ini.
- This certificate shall not reproduced except in full unless permission the reproduction of an approced
  abstract has been obtained in writing from PT. Global Promedika Services
   This certificate is valid if it has ben aproned and signed by autorized person
- . This result of calibration to be applied only for unit under test.

Halaman 1 dari 2

PT. GLOBAL PROMEDIKA SERVICES

Gedung Bersaudara Lt. 4A, Jl. Penjernihan Raya No. 38 Jakarta Pusat 10210 Telp. (021) 5743280, 5701467

www.globalpromedika.co.id