

FROM

3P Safety Training
Patrick Salazar
patrick.salazar@3psafety.net

PREPARED FOR

M.F. Engineering, Inc.
Attn: Mark Lucido
badrilling@sbcglobal.net
(925) 584-1141

EQUIPMENT & INSPECTION SCOPE

Third-Party Crane Certification Inspection — on-site visual and operational inspection performed with reference to applicable OSHA 29 CFR 1926 Subpart CC crane inspection criteria, to document equipment condition and certify the unit for continued service.

DESCRIPTION	QTY	AMOUNT
Third-party certification inspection 2019 Grove RT530E-2 rough terrain crane, Serial # 236566. Performed on-site at Ring Power, 500 World Pkwy, St. Augustine, FL 32092. Includes visual and operational inspection of structural, mechanical, hydraulic, and safety-critical systems, plus a written certification inspection report.	1 crane	\$3,295.00
TOTAL		\$3,295.00

WHAT'S INCLUDED

- On-site inspection of structural, mechanical, hydraulic, electrical, and safety-critical systems
- Inspection performed with reference to applicable OSHA 29 CFR 1926 Subpart CC crane standards
- Written certification inspection report with pass/fail findings summary
- Documentation suitable for compliance, insurance, or sale/rental purposes

Note: The crane must be accessible on-site at Ring Power and operational (engine and hydraulics running) for the inspection to be performed.

SCHEDULING & TERMS

Scheduling: Inspection date/time to be confirmed upon acceptance of this quote, subject to inspector availability.
Quote validity: This quote is valid for 30 days from the date above.
Payment: Payment is due upon completion of the inspection, unless other arrangements are confirmed in writing.

ACCEPTANCE

To accept this quote, please sign below or reply to confirm and we will contact you to schedule the inspection date.

Authorized Signature — M.F. Engineering, Inc.

Date