

Inspection Report — 300-P-309

Ultrasonic Thickness | 2026-05-11

Report ID	IR-300-P-309-2026-018
Equipment Tag	300-P-309
Equipment Name	Firewater Pump
Unit	Utilities & Offsites (300)
Inspection Date	2026-05-11
Inspection Type	Ultrasonic Thickness
Inspector	Anil Nair (Inspection Engineer, EMP-0016)
Next Due Date	2028-05-10
Governing SOP	SOP-300-009

1. Scope

Risk-Based Inspection (RBI) assessment of 300-P-309 performed by Anil Nair (Inspection Engineer, EMP-0016) in accordance with SOP-300-009 and OISD inspection guidelines.

2. Findings

Ultrasonic Thickness inspection of 300-P-309 (Firewater Pump) on 2026-05-11 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

3. Recommendation

Continue on standard RBI interval. Next inspection due 2028-05-10.