

Inspection Report — 400-T-403

Corrosion Mapping | 2024-05-11

Report ID	IR-400-T-403-2024-004
Equipment Tag	400-T-403
Equipment Name	Diesel Storage Tank
Unit	Tank Farm / Storage (400)
Inspection Date	2024-05-11
Inspection Type	Corrosion Mapping
Inspector	Sunita Patil (Inspection Engineer, EMP-0015)
Next Due Date	2024-11-07
Governing SOP	SOP-400-010

1. Scope

Risk-Based Inspection (RBI) assessment of 400-T-403 performed by Sunita Patil (Inspection Engineer, EMP-0015) in accordance with SOP-400-010 and OISD inspection guidelines.

2. Findings

Corrosion Mapping inspection of 400-T-403 (Diesel Storage Tank) on 2024-05-11 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

3. Recommendation

Continue on standard RBI interval. Next inspection due 2024-11-07.