

Inspection Report — 500-P-502

Corrosion Mapping | 2026-06-07

Report ID	IR-500-P-502-2026-038
Equipment Tag	500-P-502
Equipment Name	Effluent Transfer Pump
Unit	Effluent Treatment Plant (500)
Inspection Date	2026-06-07
Inspection Type	Corrosion Mapping
Inspector	Sunita Patil (Inspection Engineer, EMP-0015)
Next Due Date	2028-06-06
Governing SOP	SOP-500-013

1. Scope

Risk-Based Inspection (RBI) assessment of 500-P-502 performed by Sunita Patil (Inspection Engineer, EMP-0015) in accordance with SOP-500-013 and OISD inspection guidelines.

2. Findings

Corrosion Mapping inspection of 500-P-502 (Effluent Transfer Pump) on 2026-06-07 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

3. Recommendation

Continue on standard RBI interval. Next inspection due 2028-06-06.