

Inspection Report — 400-T-404

Corrosion Mapping | 2025-04-08

Report ID	IR-400-T-404-2025-005
Equipment Tag	400-T-404
Equipment Name	LPG Bullet
Unit	Tank Farm / Storage (400)
Inspection Date	2025-04-08
Inspection Type	Corrosion Mapping
Inspector	Sunita Patil (Inspection Engineer, EMP-0015)
Next Due Date	2026-04-08
Governing SOP	SOP-400-012

1. Scope

Risk-Based Inspection (RBI) assessment of 400-T-404 performed by Sunita Patil (Inspection Engineer, EMP-0015) in accordance with SOP-400-012 and OISD inspection guidelines.

2. Findings

Corrosion Mapping inspection of 400-T-404 (LPG Bullet) on 2025-04-08 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

3. Recommendation

Continue on standard RBI interval. Next inspection due 2026-04-08.