

Inspection Report — 500-P-507

Ultrasonic Thickness | 2024-05-15

Report ID	IR-500-P-507-2024-017
Equipment Tag	500-P-507
Equipment Name	Dosing Pump - Chemical
Unit	Effluent Treatment Plant (500)
Inspection Date	2024-05-15
Inspection Type	Ultrasonic Thickness
Inspector	Pooja Bhosale (Inspection Engineer, EMP-0017)
Next Due Date	2025-05-15
Governing SOP	SOP-500-014

1. Scope

Risk-Based Inspection (RBI) assessment of 500-P-507 performed by Pooja Bhosale (Inspection Engineer, EMP-0017) in accordance with SOP-500-014 and OISD inspection guidelines.

2. Findings

Ultrasonic Thickness inspection of 500-P-507 (Dosing Pump - Chemical) on 2024-05-15 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

3. Recommendation

Continue on standard RBI interval. Next inspection due 2025-05-15.