

Inspection Report — 500-P-507

External Visual | 2024-07-23

Report ID	IR-500-P-507-2024-030
Equipment Tag	500-P-507
Equipment Name	Dosing Pump - Chemical
Unit	Effluent Treatment Plant (500)
Inspection Date	2024-07-23
Inspection Type	External Visual
Inspector	Pooja Bhosale (Inspection Engineer, EMP-0017)
Next Due Date	2025-07-23
Governing SOP	SOP-500-014

1. Scope

Risk-Based Inspection (RBI) assessment of 500-P-507 performed by Pooja Bhosale (Inspection Engineer, EMP-0017) in accordance with SOP-500-014 and OISD inspection guidelines.

2. Findings

During External Visual inspection of 500-P-507 (Dosing Pump - Chemical) conducted on 2024-07-23, the inspector identified a minor severity defect: slight external pitting, remedial coating recommended. This finding has been logged against the equipment's RBI history and a follow-up inspection is scheduled for 2025-07-23.

3. Recommendation

Recommend monitoring at next scheduled interval and update of the risk-based inspection interval for 500-P-507 accordingly.