

Inspection Report — 500-P-507

Ultrasonic Thickness | 2025-03-08

Report ID	IR-500-P-507-2025-008
Equipment Tag	500-P-507
Equipment Name	Dosing Pump - Chemical
Unit	Effluent Treatment Plant (500)
Inspection Date	2025-03-08
Inspection Type	Ultrasonic Thickness
Inspector	Sunita Patil (Inspection Engineer, EMP-0015)
Next Due Date	2025-09-04
Governing SOP	SOP-500-014

1. Scope

Risk-Based Inspection (RBI) assessment of 500-P-507 performed by Sunita Patil (Inspection Engineer, EMP-0015) in accordance with SOP-500-014 and OISD inspection guidelines.

2. Findings

Ultrasonic Thickness inspection of 500-P-507 (Dosing Pump - Chemical) on 2025-03-08 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

3. Recommendation

Continue on standard RBI interval. Next inspection due 2025-09-04.