

ES Lab Report



ES Lab Continuous Monitoring System Report

Test ID	20170503-1419-CH2
Test Name	Warranty
Part Number	99070171
Customer	BMW
Channel No	2
Start Time	2017-05-03 14:21
End Time	2017-05-03 15:21
Measurement instrument	K2700
Measurement instrument serial	4093987
Climatic chamber name	Weiss WLK100
Climatic chamber serial	444444
Climatic chamber program file path	C:\Simpati\Simprog\Warranty_ - _mikrofon
Climatic chamber archive file path	C:\SIMPATI\measure\1

ES Lab Report

