



ES Lab Continuous Monitoring System Report

| | |
|------------------------------------|--|
| Test ID | 20170503-1420-CH15 |
| Test Name | Warranty |
| Part Number | 99070171 |
| Customer | BMW |
| Channel No | 15 |
| Start Time | 2017-05-03 14:21 |
| End Time | 2017-05-03 15:21 |
| Measurement instrument | K2700 |
| Measurement instrument serial | 4093987 |
| Climatic chamber name | Weiss WLK100 |
| Climatic chamber serial | 444444 |
| Climatic chamber program file path | C:\Simpati\Simprog\Warranty_ - _mikrofon |
| Climatic chamber archive file path | C:\SIMPAT\measure\1 |

ES Lab Report

