

ES Lab Report



ES Lab Continuous Monitoring System Report

Test ID	20170427-1018-CH7
Test Name	Warranty
Part Number	99070171
Customer	BMW
Channel No	7
Start Time	2017-04-27 10:19
End Time	2017-04-27 17:19
Measurement instrument	K2700
Measurement instrument serial	4093987
Climatic chamber name	Weiss WLK100
Climatic chamber serial	444444
Climatic chamber program file path	C:\Simpati\Simprog\Warranty_ - _mikrofon
Climatic chamber archive file path	C:\SIMPATI\measure\1

ES Lab Report

