



ES Lab Continuous Monitoring System Report

| | |
|------------------------------------|--|
| Test ID | 20161017-1718-CH7 |
| Test Name | Warranty |
| Test Voltage | 8 |
| Noise Source | G:\Proba\Proba\NoEQ\IEC 268-1 20-150.wav |
| Duration | 100 hours |
| Zrat | 20 |
| Prat | 4 |
| Part Number | 99070171 |
| Customer | BMW |
| Channel No | 7 |
| Start Time | 2016-10-17 17:18 |
| End Time | 2016-10-17 17:28 |
| Measurement instrument | K2700 |
| Measurement instrument serial | 4093987 |
| Climatic chamber name | Weiss WLK100 |
| Climatic chamber serial | 444444 |
| Wave File Path | G:\Proba\Proba\NoEQ\IEC 268-1 20-150.wav |
| Climatic chamber program file path | C:\Simpati\SIMPROG\ |
| Climatic chamber archive file path | C:\SIMPATI\measure\1 |

ES Lab Report

