

## ES Lab Report



# ES Lab Continuous Monitoring System Report

|                                    |                     |
|------------------------------------|---------------------|
| Test ID                            | 20170503-1537-CH13  |
| Test Name                          | Warranty            |
| Part Number                        | 99070171            |
| Customer                           | BMW                 |
| Channel No                         | 13                  |
| Start Time                         | 2017-05-03 15:38    |
| End Time                           | 2017-05-04 11:38    |
| Measurement instrument             | K2700               |
| Measurement instrument serial      | 4093987             |
| Climatic chamber name              | Weiss WLK100        |
| Climatic chamber serial            | 444444              |
| Climatic chamber program file path | C:\Simpati\Simprog\ |
| Climatic chamber archive file path | C:\SIMPAT\measure\1 |

## ES Lab Report

