

## ES Lab Report



# ES Lab Continuous Monitoring System Report

|                                    |  |
|------------------------------------|--|
| Test ID                            | 20170503-1419-CH5                        |
| Test Name                          | Warranty                                 |
| Part Number                        | 99070171                                 |
| Customer                           | BMW                                      |
| Channel No                         | 5  |
| Start Time                         | 2017-05-03 14:21                         |
| End Time                           | 2017-05-03 15:21                         |
| Measurement instrument             | K2700                                    |
| Measurement instrument serial      | 4093987                                  |
| Climatic chamber name              | Weiss WLK100                             |
| Climatic chamber serial            | 444444                                   |
| Climatic chamber program file path | C:\Simpati\Simprog\Warranty_ - _mikrofon |
| Climatic chamber archive file path | C:\SIMPATI\measure\1                     |

## ES Lab Report

