

ES Lab Report



ES Lab Continuous Monitoring System Report

Test ID	20170404-1715-CH2
Test Name	Warranty
Part Number	99070171
Customer	BMW
Channel No	2
Start Time	2017-04-04 17:15
End Time	2017-04-04 17:18
Measurement instrument	K2700
Measurement instrument serial	4093987
Climatic chamber name	Weiss WLK100
Climatic chamber serial	444444
Climatic chamber program file path	C:\Simpati\Simprog\
Climatic chamber archive file path	C:\SIMPATI\measure\0

ES Lab Report

