



## ES Lab Continuous Monitoring System Report

|                                    |  |
|------------------------------------|--|
| Test ID                            | 20161025-1346-CH3                        |
| Test Name                          | Warranty                                 |
| Test Voltage                       | 8  |
| Noise Source                       | G:\Proba\Proba\NoEQ\IEC 268-1 20-150.wav |
| Duration                           | 100 hours                                |
| Zrat                               | 20                                       |
| Prat                               | 4  |
| Part Number                        | 99070171                                 |
| Customer                           | BMW                                      |
| Channel No                         | 3  |
| Start Time                         | 2016-10-25 13:46                         |
| End Time                           | 2016-10-25 13:46                         |
| Measurement instrument             | K2700                                    |
| Measurement instrument serial      | 4093987                                  |
| Climatic chamber name              | Weiss WLK100                             |
| Climatic chamber serial            | 444444                                   |
| Wave File Path                     | G:\Proba\Proba\NoEQ\IEC 268-1 20-150.wav |
| Climatic chamber program file path | C:\Simpati\SIMPROG\                      |
| Climatic chamber archive file path | C:\SIMPATI\measure\1                     |

## ES Lab Report

