

## ES Lab Report



# ES Lab Continuous Monitoring System Report

|                                    |                      |
|------------------------------------|----------------------|
| Test ID                            | 20170404-1713-CH1    |
| Test Name                          | Warranty             |
| Part Number                        | 99070171             |
| Customer                           | BMW                  |
| Channel No                         | 1                    |
| Start Time                         | 2017-04-04 17:14     |
| End Time                           | 2017-04-04 17:14     |
| Measurement instrument             | K2700                |
| Measurement instrument serial      | 4093987              |
| Climatic chamber name              | Weiss WLK100         |
| Climatic chamber serial            | 444444               |
| Climatic chamber program file path | C:\Simpati\Simprog\  |
| Climatic chamber archive file path | C:\SIMPATI\measure\0 |

## ES Lab Report

