

ES Lab Report



ES Lab Continuous Monitoring System Report

| | |
|------------------------------------|----------------------|
| Test ID | 20170404-1401-CH2 |
| Test Name | Warranty |
| Part Number | 99070171 |
| Customer | BMW |
| Channel No | 2 |
| Start Time | 2017-04-04 14:01 |
| End Time | 2017-04-04 14:02 |
| Measurement instrument | K2700 |
| Measurement instrument serial | 4093987 |
| Climatic chamber name | Weiss WLK100 |
| Climatic chamber serial | 444444 |
| Climatic chamber program file path | C:\Simpati\Simprog\ |
| Climatic chamber archive file path | C:\SIMPATI\measure\0 |

ES Lab Report

