Quarterly Equipment Inspection Report - Plant B

Inspection ID: INS-2041

Equipment: Air Compressor AC-12

Location: Building 3, Bay 2

Inspector: R. Haddad

Date: 2025-01-14

Status: Passed

Notes: Pressure relief valve tested at 150 psi. Filters replaced. No leaks detected.

Inspection ID: INS-2042

Equipment: Forklift FL-07

Location: Warehouse North

Inspector: L. Nasser

Date: 2025-01-15

Status: Failed

Notes: Hydraulic hose on the mast is cracked and leaking fluid. Forklift tagged out of service until the hose is replaced.

Inspection ID: INS-2043

Equipment: Industrial Boiler BL-02

Location: Utility Room

Inspector: R. Haddad

Date: 2025-01-16

Status: Passed

Notes: Water level gauge and low-water cutoff operating correctly. Burner flame pattern normal.

Inspection ID: INS-2044

Equipment: Conveyor Belt CV-31

Location: Packing Line 1

Inspector: S. Khoury

Date: 2025-01-17

Status: Conditional

Notes: Belt tracking slightly off centre. Emergency stop cord functional. Re-inspect within 30 days.

Inspection ID: INS-2045

Equipment: Backup Generator GN-05

Location: Exterior Pad East

Inspector: L. Nasser

Date: 2025-01-20

Status: Passed

Notes: Load test completed for 2 hours at 80 percent load. Fuel tank at 95 percent.

Inspection ID: INS-2046

Equipment: Overhead Crane OC-01

Location: Assembly Hall

Inspector: S. Khoury

Date: 2025-01-21

Status: Failed

Notes: Wire rope shows broken strands near the hook block. Crane locked out pending rope replacement.

Inspection ID: INS-2047

Equipment: Chiller Unit CH-09

Location: Roof Level

Inspector: R. Haddad

Date: 2025-01-22

Status: Passed

Notes: Refrigerant pressure within range. Condenser coils cleaned.

Inspection ID: INS-2048

Equipment: Fire Pump FP-03

Location: Pump House

Inspector: L. Nasser

Date: 2025-01-23

Status: Passed

Notes: Weekly churn test completed. Pump reached rated pressure in 12 seconds.