Service | Pre-delivery report | RO-58006

VIN: 3VW2K7AJ5EM123456

Vehicle: Volkswagen Jetta demonstration vehicle

Visited: 2026-10-06

Related deal: DEAL-1016

Work: Fluid checks, tire inspection and battery load test

Finding: Battery below test threshold; replacement requested

Warranty reference: WC-2026-0206

Fictional sample only. Not a real transaction, policy or service record.