**PROJECTLOOP / SYNTHETIC DOCUMENT**

# Service | Pre-delivery report | RO-58010

---

VIN: JM1BM1V70E1123456

Vehicle: Mazda 3 demonstration vehicle

Visited: 2026-10-10

Related deal: DEAL-1020

Work: Fluid checks, tire inspection and battery load test

Finding: Battery below test threshold; replacement requested

Warranty reference: WC-2026-0210

Fictional sample only. Not a real transaction, policy or service record.