Service | Pre-delivery report | RO-58012

VIN: YV1RS592762123456

Vehicle: Volvo S60 demonstration vehicle

Visited: 2026-10-12

Related deal: DEAL-1022

Work: Fluid checks, tire inspection and battery load test

Finding: Battery below test threshold; replacement requested

Warranty reference: WC-2026-0212

Fictional sample only. Not a real transaction, policy or service record.