

# Device Inspection Report

## Order Information

Order Number: ORD-2026-016

Order ID: 6a1ff1d7580298c9d7b9aa4e

## Customer Information

Name: Sophie Glink

Email: sophie@mcrepair.de

Phone: 01728526121

## Technician Information

Name: Admin User

Email: admin@example.com

Inspection Date: 6/3/2026

## Inspection Results

Model: Apple iPhone 16 Pro Max

Verified: Yes

Repairable: Yes

Status: completed

## Failed Tests

- Charging: Not functioning properly

Report generated on 6/4/2026, 11:44:52 AM