CARVERTICAL

Volkswagen Golf

Generated on **11/03/2026**

VIN: **WVWZZZCD*********** | Fuel: **Gasoline** | Transmission Type: **Automatic**

Scan for full report

Commercial use check

No issues found

No records of commercial use found.

Mileage

No issues found

Last recorded mileage: 60,100 km.

Legal status check

No issues found

No financial or legal risk records found.

Damage

No issues found

No damage or assessment records found.

Theft

No issues found

No theft records found.

Natural disaster exposure

No issues found

No records of natural disaster exposure found.

+36

Data sources
We checked 1000+ data sources in **40 countries**

Commercial use check

We checked if this vehicle was used for commercial purposes - like a taxi, rental, or another service vehicle. These vehicles often see heavier use, so it's worth looking closer for signs of wear.

No issues found
No records of vehicle being used in irregular manner

Here's what we checked:

- Taxi — No record found
- Transport — No record found
- Rental — No record found
- Police — No record found
- Demo — No record found
- Driving school vehicle — No record found

Theft

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

We checked if the vehicle is currently listed as stolen, if it was ever reported stolen in the past, and whether it's been recovered.

No issues found

We didn't find any records that the vehicle was stolen.

Summary

Police database stolen vehicle check completed in **7 countries**: +1

Here's what we checked:

Is it currently wanted as stolen? ✓ No record found

Was it stolen in the past? ✓ No record found No past theft records found for this vehicle.

Police database stolen vehicle **check completed in:**

Italy Slovakia Czechia Romania Slovenia Hungary Canada

Mileage

We checked if the mileage looks accurate or if it may have been tampered with.

Summary

- Last known mileage: 60,100 km
- 7 mileage records found



This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Odometer records	
08/2022	**10 km**
11/2023	**20,638 km**
01/2024	**23,960 km**
04/2024	**30,892 km**
08/2024	**37,368 km**

Odometer records	
01/2025	**46,626 km**
11/2025	**60,100 km**

Driving habits		
08/2022 - 11/2025	**Normal driving**	**1,518 km/month**

Legal status check

We checked if the vehicle passed technical inspections and whether it was marked as scrapped.

No issues found

No records about the legal status of this vehicle were found

Legal

Passed technical inspection (MOT)? ✓ No record found

Was it scrapped? ✓ No record found

Recommended service schedule

For full past and upcoming service details, view the digital report.

Summary

- Last scheduled maintenance was 100 km ago – check what maintenance may have been required
- Based on recorded mileage, the next recommended service is due in 14,900 km

Next recommended service **at 75,000 km**

What should be serviced:

Service time approx. 48 min

Engine sump plug (Renew) | Engine oil filter (Renew) | +7 service items

Previous recommended service **at 60,000 km**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

What should have been serviced:

Service time approx. 48 min

Engine sump plug (Renew) | Engine oil filter (Renew) | +7 service items

Service time approx. 78 min

Parking brake operation (Check/report) | Instruments/warning lamps (Check/report) | Horn (Check/report)

+46 service items

Service time approx. 6 min

Cabin filter (if fitted) (Renew)

Service time approx. 30 min

Spark plugs (Renew)

Damage

Has this vehicle been damaged in the past? What was the value of the damages?

No issues found

No damage or assessment records found

Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disaster exposure

We checked if the vehicle was located in an area hit by a natural disaster at the time it happened.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

No issues found

This vehicle's location was not recorded in the area of a natural disaster.

Market price

We checked how this vehicle's market price has changed over time, based on available historical data and price estimates.

The timeline shows a limited period and does not reflect the vehicle's full lifetime pricing.

Summary

- Average market price for such vehicle: €23,400
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!



Year	Market price	↘ Lowest market value	↗ Highest market value
2025	**€24,990**	€18,850	€39,500
2026	**€23,400**	€18,850	€35,990
2027	**€23,340**	€18,802	€35,898
2028	**€22,112**	€17,813	€34,010

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Year	Market price	↘ Lowest market value	↗ Highest market value
2029	**€20,291**	€16,345	€31,208
2030	**€19,531**	€15,733	€30,039
2031	**€18,571**	€14,960	€28,563
2032	**€16,274**	€13,109	€25,030
2033	**€15,734**	€12,675	€24,200

Market price insights

Price trend forecast
This vehicle is expected to lose -33% of its market price over the next 7 years.

Price drop & buying window
The largest drop in market price is expected around 2032, when the vehicle reaches 10 years of age. Buying around this time may offer better value.

Optimal selling timing
Selling before the largest price drop – expected around 2031 or 9 years of age – may help retain more value.

Note: Forecasts are based on current market trends and historical data. Actual resale value may change due to market shifts, condition, location, or other factors.

Specs & equipment

The vehicle's technical specifications and original equipment on record.
This section includes simplified AI-generated descriptions to help you better understand each vehicle feature.

Summary
Make sure the vehicle's specs and equipment match what the seller told you.

Identification and technical specifications

Make
Volkswagen

Model
Golf

Body type
Hatchback

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Model year **2022**	Powertrain displacement **2 L**	Powertrain power **221 kW (296 hp / 300 PS)**
Fuel type **Gasoline**	Transmission type **Automatic**	Drive type **FWD**
Number of doors **5**	Steering wheel placement **LHD**	Number of cylinders **4**
Number of gears **7**	Engine description **["2.0 TSI"]**	Model market **EU**

Equipment

As received from the manufacturer

0AE Front stabilizer

Front stabilizer included

0B1 Wheelbase

Wheelbase

0BG Rear stabilizer

Rear stabilizer

0F1 Fuel system for SI engine, ethanol fuel

Fuel system optimized for SI engine with capability to use ethanol fuel

0FA Standard manufacturing sequence

Manufacturing Sequence Followed as Standard

0IJ Installation differentiation for transmission "DQ381" -- vehicle components --

Installation Differentiation for Transmission 'DQ381' Components

0K0 Without alternative drive system

No Alternative Drive System Installed

0KA Without decals and emblems

Without decals and emblems

0N4 4-link rear suspension

[illegible]

0NH Nameplate set "GTI"

[illegible]

0P8 Exhaust system (exhaust sound)

[illegible]

0TD Floor mats in front and rear

[illegible]

0XY Information kit in German (for Austria)

[illegible]

0Y1 Standard climatic zones

[illegible]

0YD Weight range 4 installation control only, no requirement forecast

[illegible]

1AQ BRS for vehicles without electric drive (ESC and electric brake booster)

[illegible]

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

1D0 Without trailer hitch

1E5 Activated carbon canister for intensified evaporation system with on-board diagnostic system 2

1EX Special identification plate for EC for M1 passenger vehicle

1G8 Breakdown kit

1J2 Sound deadening package and additional enclosures for some units

1KJ Disk brakes in rear

1LP Disk brakes in front

1PE Wheel bolts with anti-theft protection (unlockable)

1S1 Tool kit and jack

1SA Without additional front underbody guard

1T2 Warning triangle

1X0 Front wheel drive

1Y2 Front differential lock

1Z0 Initial standard fuel filling

20A Without electric motor (hybrid)

2CM Vehicle class differentiation 5H0

2F0 Without locking and starting systems

2I0 Adaptive chassis control with continuousoperation

2JI Bumpers

2KW Labels/plates in German, French, and Dutch

2PT Leather-wrapped steering wheel for airbag system with additional mass

2WA Without additional tires

31K Front and rear license plate carrier (ECE)

3C7 3-point seat belt for center rear seat

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

3CA Without partition

3D3 Center console

3FB Spoiler roof

3H0 Without backrest release for front seats

3J9 Head restraint for front seat

3L3 Manual height adjustment for front seats

3LJ Door and side trim panel in foam film, insert in leatherette

3NU Rear seat bench unsplit, backrest split folding with center armrest

3QT 3-point seat belts in front, with pretensioner and height adjustment

3S0 Without roof rails/roof load rack

3T2 Three rear head restraints

3ZU 3-point seat belts, outer rear with ECE label

4A3 Seat heater for front seats separately controlled

4D0 Without seat ventilation/massage seat

4E0 Tailgate/trunk lid unlocking from outside

4G3 Storage compartment, left and right 1st row of seats

4GF Windshield in heat-insulating glass

4K5 Central locking system "Keyless Entry" with fingerprint

4KF Side windows in heat-insulating glass, from B-pillar and rear window dark tinted

4L6 Breakaway interior rearview mirror, auto-dimming

4P0 Rear floor panel module, type 1

4UF Driver and front passenger airbag with front passenger airbag deactivation

4X3 Side airbag in front, with curtain airbag

4ZQ Without additional moldings

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

5C0 Without special body measures

5F1 1 armrest for left front seat and 2 armrests for right front seat

5J4 Body-colored rear spoiler

5JA Without ambulance seat for medical staff

5K7 Transport protection film (minimum protection) with additional transport protection measures

5MR Decorative inserts

5XJ Sun visors with mirror, illuminated, with airbag label on sun visor and B-pillar

6A0 Without fire extinguisher

6E3 Center armrest in front

6FJ Black exterior mirror housings

6I6 Lane keeping system plus semi-automatic vehicle control in a medical emergency and traffic jam assist

6NA Unsplit molded headliner

6Q6 Aluminum gearshift knob/handle

6T2 Interior light in footwell in front and rear

6XQ Exterior mirrors: with memory feature, power-folding/adjustable, separately heated

6Y9 Without speed limiter

76A Without mode 3 charging cable

7AA Electronic engine immobilizer

7B2 12-volt socket in luggage boot

7E0 Without heat accumulator/auxiliary heater

7K1 Direct tire pressure monitoring system

7L6 Start/stop system with regenerative braking

7P4 Manually adjustable lumbar support in front seats

7U0 Standard engine starter

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

7UG Navigation system - High

7W0 Without extended safety system

7X2 Park distance control in front and rear

7Y1 Lane change assist

8AR Radio "gamma" with removable operating panel

8FA Without second battery

8G5 Multiple matrix beam

8GU Alternator 140 A

8IU LED headlamps with variable light distribution

8J3 Hand brake/low brake fluid level warninglight and inscription

8N6 Windshield wiper intermittent control with light/rain sensor

8Q5 Headlight range adjustment, automatic/ dynamic, with cornering light (AFS 1)

8S4 Two reading lights in front, two in rear

8T8 Adaptive cruise control (with "follow-to-stop") and speed limiter

8WP Front fog lamp, cornering and all-weather light

8X7 Without headlamp washer system / with washer fluid level indicator

8Y1 Two-tone horn

8Z5 Not hot country

8ZQ Antenna for FM reception only, diversity

9D0 Without preparation for two-way radio installation

9F0 Without sound combination for rotating emergency light and radio antenna preparation

9I5 Separate daytime running lights with automatic headlamp activation and Coming Home feature (automatic)

9IJ Comfort telephony with LTE and wireless charging

9JA Non-smoker's package

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

9M0 Without auxiliary heater/fuel-fired parking heater

9P4 Seat belt reminder, electric contact in front and rear, visual and acoustical

9T1 Heated washer nozzles in front

9VG Sound system with subwoofer "branded" design 2

9WJ Power supply/TV signal for customized installation

9Z0 Operating voltage 12 V

A8H Top sports equipment

AV1 Driving on the right

B0A Component parts set without country-specific building regulation

B12 Type approval country Austria

C17 Operating permit, alteration

C6J Steel wheels 6J x 14, SEAT, black ET38

DS4 4-cylinder SI engine 2.0 l/221 kW TFSI, homogeneous base engine is TT6

E4H "Summer"

EA8 3 years follow-on warranty, max. 100 000 km

EL5 Online service, with OCU, with head unitcoding, without engine immobilizer interconnection

EM1 Driver alert system

ER1 Regional code " ECE " for radio

EV0 Without charging cable

F0A No special purpose vehicle, standard equipment

FB0 Standard paint coating

FC0 Without customized installation

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

FM0 Basic equipment variant

G1C Seven-speed automatic transmission

G26 Shock absorption in front

GM1 Standard electronic engine sound

GP0 Vehicles without special upgrade measures

GW2 Car2X "High" variant

H13 Tires 235/35 R19 91Y

IG0 Standard curb weight range

J0V Battery 420 A (70 Ah)

K8G Hatchback

KA2 With rear view camera system (type 2)

KH7 Climatronic (3-zone) with rear air conditioning control panel

KK3 Refrigerant R1234yf

KS1 Head-up display

L0L Left-hand drive

L53 Suspension range 53 installation control only, no requirement forecast

N2Z Seat trim covers for special editions

NY0 Standard battery/alternator capacity

NZ4 Private emergency call system

Q4P Sports seats in front

QG1 Service interval prolongation

QH1 Voice control

QI6 Service indicator 30 000 km or 2 years (variable)

QJ1 Chrome package

QK1 With multifunction camera

QQ4 With additional lights (interior lighting)

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

QR9 With dynamic road sign display

QV3 Digital radio reception

QZ0 Speed-related variable steering assist (Servotronic) w/ reduced steering height

S7Y Growth strategy Sri Lanka/Bangladesh

U5A Instrument cluster, km/h speedometer

U9C 2 x USB type C

UB2 Rear shock absorption for sports version

UG0 Without hill start assist/hill descent control/comfort driving assist

UH2 Parking brake

UK1 Standard rear seat release

V1P Tire suppliers for EU countries

VF1 Pedal cluster

VL1 Extended pedestrian protection measures

X4A Equipment options subset for Austria

+36

Data sources
We checked 1000+ data sources in **40 countries**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Helpful tips after reading the report

Every tip you check off helps you avoid unwelcome surprises later. The more you check, the safer your car deal.

Do these checks before buying a car:

- [ ] **Get a professional inspection**

  An expert mechanic can spot hidden issues you might miss. Here's what to do next:

  - [ ] Book a pre-purchase inspection at an independent or authorised service
  - [ ] Ask the mechanic to check key systems: engine, brakes, suspension, electronics
  - [ ] Request written notes or a report of any issues found

- [ ] **Ask for service records**

  Service records show how well the car has been looked after. Here's what to do next:

  - [ ] Ask the seller for the car's service book or maintenance records
  - [ ] Check for regular oil changes, filter replacements, and timing belt work
  - [ ] Note any missing or overdue services

- [ ] **Check if the mileage matches**

  Make sure the mileage in this report matches the car's odometer readings. Your latest known mileage is **60,100 km**. Here's what to do next:

  - [ ] Check the odometer reading against the mileage in the report
  - [ ] Watch for signs of tampering (worn pedals, suspicious dashboard fixes)
  - [ ] Ask the seller about any differences

- [ ] **Take a real test drive**

  A proper test drive helps you spot problems with performance, handling, or comfort – you'll notice much more on the road than you will in the parking lot. Here's what to do next:

  - [ ] Drive on different road types: highway, city traffic, and bumpy or uneven surfaces
  - [ ] Listen for strange noises or vibrations
  - [ ] Pay attention to handling and comfort

- [ ] **Compare with similar cars**

  Checking other listings helps you know if the asking price is fair – or worth negotiating. Here's what to do next:

  - [ ] Search for similar cars online (same make, model, year, mileage)
  - [ ] Compare asking prices
  - [ ] Look at car condition and equipment
  - [ ] Use this info to negotiate with the seller

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.