

No. Dok. : FM-LAP- D2-SOP-003-011	Formulir Preventive Maintenance Pole / Tower	
Versi : 1.0		
Hal : 1 dari 1		
Label : Internal		

Location : Grand Mall Bekasi
 Date / time : Rabu 22 Mei 2025
 Type Pole : SST/Pole/Tripole/Triangle/Triangle Wired

No.	Descriptions	Result	Operational Standard	Status (OK/NOK)
1.	Physical Check			
	a. Foundation Condition	Normal	Condition: No cracks and no settlement in the building's soil or concrete structure.	OK
	b. Pole/Tower Foundation Flange/Base Plate Condition	Normal	No rust, no metal cracks, structurally strong.	OK
	c. Pole/Tower Support Flange/Base Plate Condition	Normal	No rust, no metal cracks, structurally strong.	OK
	d. Flange Condition at Each Pole/Sling Connection Point	Normal	Structurally strong and securely fastened	OK
	e. Pole / Tower Condition	Normal	No rust	OK
	f. Arm Antenna Condition	Normal	No rust, no metal cracks, structurally strong.	OK
	g. Availability BasBar Ground	Normal	Available / Not Avail	OK
	h. Bonding Bar	Normal	Available / Not Avail, if Available No rust, no metal cracks	OK
2.	Performance Measurement			
	a. Inclination Measurement	90	Waterpass reading: 90° inclination $\pm 2^\circ$ tolerance	OK

Notes / additional informations :

<u>Pole kondisi Normal</u>

Executor				Verifikator	Head Of Sub Departement
No	Nama	Mitra / Internal	Signature		
1	Azki	IMS		(_____) (_____)	
2					
3					
4					