

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: 5S Audit

Department: Capping

Document Number: INSP-254
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-254
Type	5S Audit
Date & Time	2023-09-20 11:07
Location / Department	Capping
Inspector	Anita Desai (QC Manager)
Overall Score / Result	88%

2. Scope & Methodology

This report covers the 5S Audit conducted in the Capping department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
CM104	Tools left on floor.	Failed	High
CM102	Floor marking faded.	Failed	Medium
CM103	Floor marking faded.	Failed	Medium
CM102	Floor marking faded.	Failed	Medium

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Anita Desai
Date: 2023-09-20