

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: Safety Walkaround

Department: Labeling

Document Number: INSP-104
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-104
Type	Safety Walkaround
Date & Time	2023-02-21 11:18
Location / Department	Labeling
Inspector	Farah Shaikh (Food Safety Officer)
Overall Score / Result	Pass (with observations)

2. Scope & Methodology

This report covers the Safety Walkaround conducted in the Labeling department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
LB103	Trip hazard (cable) present.	Failed	High
General Area	Fire extinguisher blocked.	Failed	High
LB101	E-Stop button unobstructed.	Passed	Low
LB103	Fire extinguisher blocked.	Failed	High
LB103	Guard securely bolted.	Passed	Low
LB101	Fire extinguisher blocked.	Failed	Medium

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Farah Shaikh
Date: 2023-02-21