

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: Safety Walkaround

Department: Utilities

Document Number: INSP-143
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-143
Type	Safety Walkaround
Date & Time	2023-04-10 17:12
Location / Department	Utilities
Inspector	Anita Desai (QC Manager)
Overall Score / Result	Pass (with observations)

2. Scope & Methodology

This report covers the Safety Walkaround conducted in the Utilities department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
UPS104	Guard securely bolted.	Passed	Low
General Area	E-Stop button unobstructed.	Passed	Low
UPS103	Fire extinguisher blocked.	Failed	High
General Area	Fire extinguisher blocked.	Failed	Medium
DG103	Trip hazard (cable) present.	Failed	High
BL102	Trip hazard (cable) present.	Failed	High
CH104	Guard securely bolted.	Passed	Low

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Anita Desai
Date: 2023-04-10