

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: 5S Audit

Department: Water Treatment

Document Number: INSP-049
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-049
Type	5S Audit
Date & Time	2023-01-24 12:08
Location / Department	Water Treatment
Inspector	Anita Desai (QC Manager)
Overall Score / Result	82%

2. Scope & Methodology

This report covers the 5S Audit conducted in the Water Treatment department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
P103	Workstation clean.	Passed	Low
P103	Floor marking faded.	Failed	Medium
General Area	Tools left on floor.	Failed	High
P104	Tools left on floor.	Failed	High
General Area	Tools left on floor.	Failed	Medium
TK102	Floor marking faded.	Failed	High

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Anita Desai
Date: 2023-01-24