

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: Hygiene & Sanitation Inspection

Department: Water Treatment

Document Number: INSP-259
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-259
Type	Hygiene & Sanitation Inspection
Date & Time	2023-05-13 07:10
Location / Department	Water Treatment
Inspector	Farah Shaikh (Food Safety Officer)
Overall Score / Result	83%

2. Scope & Methodology

This report covers the Hygiene & Sanitation Inspection conducted in the Water Treatment department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
General Area	Water pooled under machine.	Failed	Medium
General Area	Sanitizer station empty.	Failed	Medium
P101	Residue found on external cover.	Failed	High
WT102	Residue found on external cover.	Failed	Medium
General Area	CIP logs up to date.	Passed	Low
General Area	Sanitizer station empty.	Failed	Medium

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Farah Shaikh
Date: 2023-05-13