

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: Safety Walkaround

Department: Water Treatment

Document Number: INSP-077
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-077
Type	Safety Walkaround
Date & Time	2023-03-22 11:24
Location / Department	Water Treatment
Inspector	Farah Shaikh (Food Safety Officer)
Overall Score / Result	Pass (with observations)

2. Scope & Methodology

This report covers the Safety Walkaround conducted in the Water Treatment department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
WT104	Trip hazard (cable) present.	Failed	Medium
TK101	Fire extinguisher blocked.	Failed	High
TK105	Guard securely bolted.	Passed	Low
TK105	Trip hazard (cable) present.	Failed	Medium
TK101	Guard securely bolted.	Passed	Low
WT101	Guard securely bolted.	Passed	Low
P104	Guard securely bolted.	Passed	Low
TK104	Fire extinguisher blocked.	Failed	Medium

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Farah Shaikh
Date: 2023-03-22