

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: Safety Walkaround

Department: Filling

Document Number: INSP-105
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-105
Type	Safety Walkaround
Date & Time	2023-08-02 17:18
Location / Department	Filling
Inspector	Rajesh Kulkarni (Plant Manager)
Overall Score / Result	Pass (with observations)

2. Scope & Methodology

This report covers the Safety Walkaround conducted in the Filling department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
General Area	Trip hazard (cable) present.	Failed	High
General Area	Fire extinguisher blocked.	Failed	Medium
FM103	Trip hazard (cable) present.	Failed	Medium
FM102	E-Stop button unobstructed.	Passed	Low
General Area	Trip hazard (cable) present.	Failed	High
FM104	Guard securely bolted.	Passed	Low
FM104	Fire extinguisher blocked.	Failed	High

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Rajesh Kulkarni
Date: 2023-08-02