

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: Hygiene & Sanitation Inspection

Department: Labeling

Document Number: INSP-013
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-013
Type	Hygiene & Sanitation Inspection
Date & Time	2023-05-10 17:22
Location / Department	Labeling
Inspector	Rajesh Kulkarni (Plant Manager)
Overall Score / Result	86%

2. Scope & Methodology

This report covers the Hygiene & Sanitation Inspection conducted in the Labeling department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
LB103	Residue found on external cover.	Failed	Medium
LB103	CIP logs up to date.	Passed	Low
LB101	Residue found on external cover.	Failed	High
General Area	Sanitizer station empty.	Failed	Medium
LB103	Residue found on external cover.	Failed	High
General Area	CIP logs up to date.	Passed	Low

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Rajesh Kulkarni
Date: 2023-05-10