

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: Equipment Condition Audit

Department: Bottle Washing

Document Number: INSP-068
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-068
Type	Equipment Condition Audit
Date & Time	2023-06-22 15:26
Location / Department	Bottle Washing
Inspector	Rajesh Kulkarni (Plant Manager)
Overall Score / Result	Pass (with observations)

2. Scope & Methodology

This report covers the Equipment Condition Audit conducted in the Bottle Washing department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
BW103	No visible leaks.	Passed	Low
BW102	Panel door loose.	Failed	Medium
BW102	Panel door loose.	Failed	Medium
BW105	Minor oil weep from gearbox.	Failed	High
BW103	No visible leaks.	Passed	Low

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Rajesh Kulkarni
Date: 2023-06-22