

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: 5S Audit

Department: Water Treatment

Document Number: INSP-282
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-282
Type	5S Audit
Date & Time	2023-04-15 11:58
Location / Department	Water Treatment
Inspector	Anita Desai (QC Manager)
Overall Score / Result	88%

2. Scope & Methodology

This report covers the 5S Audit conducted in the Water Treatment department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
General Area	Shadow board organized.	Passed	Low
General Area	Floor marking faded.	Failed	High
WT103	Floor marking faded.	Failed	Medium
WT103	Floor marking faded.	Failed	High
TK101	Workstation clean.	Passed	Low
General Area	Tools left on floor.	Failed	Medium
General Area	Shadow board organized.	Passed	Low

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Anita Desai
Date: 2023-04-15