

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: 5S Audit

Department: Filling

Document Number: INSP-195
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-195
Type	5S Audit
Date & Time	2023-11-11 10:35
Location / Department	Filling
Inspector	Farah Shaikh (Food Safety Officer)
Overall Score / Result	83%

2. Scope & Methodology

This report covers the 5S Audit conducted in the Filling department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
General Area	Shadow board organized.	Passed	Low
FM101	Workstation clean.	Passed	Low
FM103	Tools left on floor.	Failed	Medium
FM102	Floor marking faded.	Failed	Medium
FM104	Shadow board organized.	Passed	Low
General Area	Shadow board organized.	Passed	Low

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Farah Shaikh
Date: 2023-11-11