

INSPECTION REPORT

Q1 Structural Assessment

Downtown Office Complex

CLIENT

Metropolis Real Estate

101 Main St, Cityville

PROJECT SITE

Structural inspection of the main tower and parking garage.

REPORT DATE

March 1, 2026

PREPARED BY

Jane Engineer

INSPECTION FINDINGS

SECTION 01 / TECHNICAL OBSERVATIONS

OBSERVATIONS & NOTES

Observed vertical hairline crack extending 20cm. Requires monitoring.

LOCATION

Basement Level 2

RESPONSIBLE

Jane Engineer

VISUAL EVIDENCE



