



CMC Bio Filter Service

INVOICE

Service Date: 7 March 2026

Work Completed

- Electrical control systems checked – all functioning correctly.
- All five pumps operational.
- Biofilter pumps removed, checked, and cleaned.
- Biofilter tank emptied using vacuum tanker.
- Pumps reinstalled.
- Biofilter tank jet washed.

System Status

The system was left in good working order.

Engineer

Manny

Next Action

Primary tank scheduled to be emptied next week.

Spring biofilter costs	£625.00
Payee	Christine McCann
Account number	96324432
Sort code	60-84-07