

OFFICIAL ACCIDENT REPORT



Report Number	ACC-2026-237646	Report Date	June 04, 2026 22:54
Accident Location	Fatimah Bint Asad Street, Al Sharq, Sharjah, Sharjah Emirate	Emirate	Sharjah
Accident Severity	Moderate	GPS Coordinates	25.3645° N, 55.3948° E
Authorized Estimate	AED 796.88	Coverage	80%
Claim ID	claim_owner_1780599237646	Workshop	ProFix Auto Center — Dubai

1. Incident Context & Conditions

Time of Incident	2026-06-04	Road Type	Normal traffic — dry road
Weather Condition	Clear / dry	Lighting	Full artificial streetlight

Brief Description of Circumstances

The inspection detected: Light — Lamp Crack, Door — Scratch, Fender — Scratch, Scratch, Part Crack, Glass Crack. Safety-critical damage identified on Light — Lamp Crack, Glass Crack requires immediate attention.

Detected damage: Light — Lamp Crack: Lamp Crack (80.2% confidence); Door — Scratch: Scratch (65.1% confidence); Fender — Scratch: Scratch (88.7% confidence); Door — Scratch: Scratch (48.7% confidence); Scratch: Scratch (76.8% confidence); Part Crack: Part Crack (74.8% confidence); Part Crack: Part Crack (69.8% confidence); Glass Crack: Glass Crack (60.1% confidence)

2. Vehicle 1 (Reporting / Liable Party)

Plate Number	9/24567	Vehicle Responsibility	Under review
Make & Model	LEXUS LEXUS-SUV-TEST (2024)	Policy / Insurer	ADNIC-987654321 ADNIC INSURANCE
Chassis Number (VIN)	JTHBK1GG7R1234567	Mulkiya Expiry	20-AUG-2026
Driver / Owner	Faizal Khan	Garage Assigned	ProFix Auto Center — Dubai

Identified Damage Areas

Light — Lamp Crack (Moderate, 80%); Door — Scratch (Minor, 65%); Fender — Scratch (Minor, 89%); Door — Scratch (Minor, 49%); Scratch (Minor, 77%); Part Crack (Moderate, 75%)

First Party Signature ■■■■■■■ ■■■■■■ ■■■■■■ (■■■■■■■■)	Second Party Signature ■■■■■■■ ■■■■■■ ■■■■■■ (■■■■■■■■)
AUTOVAULT Verification Authority ■■■■■■■ ■■■■■■ ■■■■■■ ■■■■■■	