VEHICLE INSPECTION REPORT

AI-Powered · April 06, 2026 at 15:41

VIN / Registration	ABC123456789XY001	Mileage	45,000
Make / Model	FICTION-MOTORS FICTION-SUV-TEST	Year	2024

AI Vehicle Health Assessment

64/100

Vehicle Health Score

Risk Level	**Medium**	**Overall Status**	**FAIL**

Key Risk Factors:

- Safety-critical components affected: Windshield Damage, Light Damage
- Minor cosmetic damage on: Bumper Damage

AI Inspection Summary

The inspection detected damage to: Windshield Damage, Bumper Damage, Light Damage. Safety-critical damage was identified on Windshield Damage, Light Damage, requiring immediate attention. Professional repair is strongly recommended before continued vehicle use.

Defect Analysis

Windshield — Windshield Crack ■ Safety-Critical (Moderate, 70.4% confidence)
Windshield cracks or chips impair driver visibility and compromise cabin structural integrity — repair or replace immediately before driving.

Bumper — Bumper Dent / Crack (Moderate, 59.4% confidence)
Bumper damage is primarily cosmetic but reduces impact absorption in future collisions — repair recommended to restore safety rating.

Light — Light Cover Scratch ■ Safety-Critical (Minor, 45.5% confidence)
Damaged lights reduce visibility and road legality — replace affected light units before driving at night or in poor conditions.

AI Recommendations

1. Windshield cracks or chips impair driver visibility and compromise cabin structural integrity — repair or replace immediately before driving.

2. Bumper damage is primarily cosmetic but reduces impact absorption in future collisions — repair recommended to restore safety rating.

3. Damaged lights reduce visibility and road legality — replace affected light units before driving at night or in poor conditions.

Damage Inspection Checklist

Component	Defect Type	Confidence	Severity
Bonnet	No Damage Detected	—	—
Bumper	Bumper Dent / Crack	59.4%	Moderate
Dickey	No Damage Detected	—	—
Door	No Damage Detected	—	—
Fender	No Damage Detected	—	—
Light	Light Cover Scratch	45.5%	Minor ■
Windshield	Windshield Crack	70.4%	Moderate ■
Total Unique Defects	**3**	**Overall Status:**	**FAIL**

Defects Identified — Annotated Images

Note: This report was generated using AI-powered computer vision (Roboflow) and large language model analysis (Groq LLaMA 3.3). Results are based on provided images and should be verified by a qualified technician for critical decisions or insurance purposes.